AnnexureD

BUILDINGSAFETYCERTIFICATE

No. 125/Camp/AE/25-26 Dated: 28/10/25

It is certified that the existing building ...Shri Krishnam Public School (name of the building or premises) at .....Sakarva Road Goverdhan., Mathura.....

..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+1	X	X	X	X	X

The building is owned/occupied by.....Shri Krishnam Public School.....(name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Works department (Name of Department/ Govt.) on....28/10/25.....(date of inspection) in the presence of .....Mr. Hare Krishna Sharma..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from..28/10/25....for a period of.....02..... years in accordance With rule and subject to compliance of the specific conditions as appended.

1.
2. —NA—
3.
4.

Issued on....28/10/25.....at.....Mathura.....by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name : Sultan Singh

Designation : ~~सहायक अभियंता~~ निर्माण खण्ड 1 लो०नि०वि० मथुरा।

Name & Address of Department